

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905153**FIELD INSPECTION FORM**
 Loc ID 325589 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name     | Phone          | Email                        | Comment                           |
|------------------|----------------|------------------------------|-----------------------------------|
| Stevens, Glenn   | (970) 749-0192 | glennstevens@centurylink.net |                                   |
| Labowskie, Steve |                | steve.labowskie@state.co.us  |                                   |
| Callahan, Linda  | (918) 712-8828 | lcallahan3@swbell.net        | <a href="#">e-mail receipient</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 215051      | WELL | PR     | 03/01/2019  | OW         | 067-06656 | SCHMITT ESTATE 2-36 | PR          |

**General Comment:**[This is a site inspection with photos at the end of this report.](#)

| Location   |   |          |      |         |                  |
|--|---|----------|------|---------|------------------|
| <b>Lease Road:</b>                                     |   |          |      |         |                  |
| Type   | Access  |          |      |         |                  |
| comment:   | Two track dirt road across private property.  |          |      |         |                  |
| Corrective Action                                      | L   |          |      |         | Date:            |
| Overall Good: <input type="checkbox"/>                 |   |          |      |         |                  |
| <b>Signs/Marker:</b>                                   |   |          |      |         |                  |
| Type   | WELLHEAD  |          |      |         |                  |
| Comment:   | Sign posted at wellhead.  |          |      |         |                  |
| Corrective Action:                                     |   |          |      |         | Date:            |
| Emergency Contact Number:                              |   |          |      |         |                  |
| Comment:   | Emergency contact information and 911 posted on sign.   |          |      |         |                  |
| Corrective Action:                                     |   |          |      |         | Date: _____      |
| <b>Good Housekeeping:</b>                              |   |          |      |         |                  |
| Type   | WEEDS   |          |      |         |                  |
| Comment:   | Weeds are overgrown around pumping unit.  |          |      |         |                  |
| Corrective Action:                                     | Remove weeds to comply with Rule 603.f.   |          |      |         | Date: 07/25/2019 |
| Overall Good: <input type="checkbox"/>                 |   |          |      |         |                  |
| <b>Spills:</b>   |   |          |      |         |                  |
| Type   | Area  | Volume   |      |         |                  |
| In Containment: No                                     |   |          |      |         |                  |
| Comment: _____   |   |          |      |         |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |   |          |      |         |                  |
| <b>Fencing/:</b>                                       |   |          |      |         |                  |
| Type   | PUMP JACK   |          |      |         |                  |
| Comment:   | Hog panels around wellhead and pumpjack.  |          |      |         |                  |
| Corrective Action:                                     |   |          |      |         | Date:            |
| <b>Equipment:</b>                                      |   |          |      |         |                  |
| Type: Ancillary equipment                              | # 1   |          |      |         | corrective date  |
| Comment:   | Wellhead has stained soil from oily waste around it.  |          |      |         |                  |
| Corrective Action:                                     | Properly treat or dispose of oily waste in accordance with 907.e.   |          |      |         | Date: 08/15/2019 |
| Type: Pump Jack  | # 1   |          |      |         |                  |
| Comment:   | Pumpjack engine is leaking engine oil and staining soil around it.  |          |      |         |                  |
| Corrective Action:                                     | Properly treat or dispose of oily waste in accordance with 907.e. and Rule 605.d.                                 |          |      |         | Date: 08/15/2019 |
| Type: Flow Line  | # 2   |          |      |         |                  |
| Comment:   | 1-2" flowline from wellhead to centralized tank battery. 1-1" flowline from wellhead to pumpjack engine fuel gas. |          |      |         |                  |
| Corrective Action:                                     |   |          |      |         | Date:            |
| <b>Tanks and Berms:</b>                                |   |          |      |         |                  |
| Contents   | #   | Capacity | Type | Tank ID | SE GPS           |

|  |          |                     |                     |             |   |                  |
|--|----------|---------------------|---------------------|-------------|---|------------------|
| CRUDE OIL  | 2        | 300 BBLs            | STEEL AST           |             | , |                  |
| Comment: NFPA labeling on centralized tank battery is not legible. |          |                     |                     |             |   |                  |
| Corrective Action: Replace labels on tanks per Rule 210.d.         |          |                     |                     |             |   | Date: 08/15/2019 |
| <u>Paint</u>   |          |                     |                     |             |   |                  |
| Condition  | Adequate |                     |                     |             |   |                  |
| Other (Content)  |          |                     |                     |             |   |                  |
| Other (Capacity)   |          |                     |                     |             |   |                  |
| Other (Type)   |          |                     |                     |             |   |                  |
| <u>Berms</u>   |          |                     |                     |             |   |                  |
| Type   | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |   |                  |
| Earth  | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |   |                  |
| Comment:   |          |                     |                     |             |   |                  |
| Corrective Action:   |          |                     |                     |             |   | Date:            |
| <u>Venting:</u>  |          |                     |                     |             |   |                  |
| Yes/No   | NO       |                     |                     |             |   |                  |
| Comment:   |          |                     |                     |             |   |                  |
| Corrective Action:   |          |                     |                     |             |   | Date:            |
| <u>Flaring:</u>  |          |                     |                     |             |   |                  |
| Type   |          |                     |                     |             |   |                  |
| Comment:   |          |                     |                     |             |   |                  |
| Corrective Action:   |          |                     |                     |             |   | Date:            |

| Inspected Facilities |            |       |      |             |           |         |    |               |    |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 215051     | Type: | WELL | API Number: | 067-06656 | Status: | PR | Insp. Status: | PR |
| Producing Well       |            |       |      |             |           |         |    |               |    |
| Comment:             | Producing. |       |      |             |           |         |    |               |    |
| Corrective Action:   |            |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Ditches          | Pass            | Culverts                | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                        | URL   |
|--------------|------------------------------------|---|
| 402109538    | INSPECTION SUBMITTED               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879093</a> |
| 687905163    | Oil leak from engine/stained soil. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879066">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879066</a> |
| 687905164    | Stained soil around wellhead.      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879067</a> |
| 687905165    | Weeds around equipment.            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879068">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879068</a> |
| 687905166    | Labeling on tank battery.          | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879069">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879069</a> |