

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905162**FIELD INSPECTION FORM**

Loc ID 325540 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214975	WELL	PR	02/01/2019	GW	067-06580	HARRIS, RUSSELL 1	PR

General Comment:[Site inspection with photos at the end of this report.](#)

Location

Lease Road:			
Type	Access		
comment:	Two-track dirt road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards are falling off or disintegrated.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/15/2019

Emergency Contact Number:

Comment: Emergency contact information and 911 posted on sign.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 2		
Comment:	1-2" flowline from wellhead to centralized crude oil tank battery. 1-1" flowline from wellhead to pumpjack engine fuel gas.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pumpjack in broken and currently not operable.		
Corrective Action:	Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/15/2019
Type: Ancillary equipment	# 1		
Comment:	Wellhead has stained soil around it.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date:	08/15/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	See corrective action under tanks/labels.				
Corrective Action:		Date:			

Paint

Inspector Name: Stewart, Joseph

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	214975	Type:	WELL	API Number:	067-06580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402109558	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879114
687905183	Broken down pumpjack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879086
687905184	Stained soil around wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879087
687905185	Inadequate labeling on tanks.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879088
687905186	Inadequate labeling on tanks.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879089