

Inspection Photos

API: 05-071-07915

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 7/19/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 1. Stormwater is flowing down the road causing erosion. Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 2. These two diversion ditches are transporting sediment offsite. No BMP's installed. Sediment trap or check damns would prevent sediment transport offsite. Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 3. Stormwater is running down the road and is scouring the road. No BMP's installed. Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 4. The photo on left is culvert inlet filled with sediment. Photo right is damaged culvert near outlet. Lat/Long:37.00845,-104.84245
Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 5. This culvert is filled in with sediment and damaged.

Lat/Long:37.00817,-104.84711



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 6. Facing toward the location. Red arrow points to List B noxious weeds. Some of the weeds were wilting from weed control but others were not treated. The cut slope is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 7. There are numerous first year Houndstongue that have not been controlled along the cut slope. The cut slope is not stabilized. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019

Inspection Photos



Photo 8. There are numerous first year Musk thistle at the location which have not been controlled. Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 7/19/2019