

# Inspection Photos

API: 05-071-09061

Operator: ARP PRODUCTION COMPANY  
WAPITI OPERATING LLC

Inspection Date: 7/19/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 7/19/2019

## Inspection Photos



**Photo 1.** Facing toward the location. Red arrow points to erosion issues that have not been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 7/19/2019



## Inspection Photos



**Photo 2.** There is List B noxious weeds growing along the cut slope. (Musk thistle shown in photo)

Corrective action was not completed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 7/19/2019



## Inspection Photos



**Photo 3.** There were some noxious weeds along the fill slope that were treated and others that did not. Weed control was poorly done.

Corrective action was not completed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 7/19/2019