

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/22/2019

Document Number:

687905273**FIELD INSPECTION FORM**Loc ID 333564 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215235	WELL	PR	02/14/1986	GW	067-06840	ZELLITTI 1 A	PR
291757	WELL	PR		GW	067-09384	ZELLITTI A 3	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on sign at tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 15		
Comment:	2-3" flowlines from wellheads to separator. 2-2" flowlines from separator blowdown to produced water tank. 2-2" flowlines from separator dump valve to offsite gathering system. 2-2" flowlines from separator dump valve to produced water tank. 2-3" flowlines from separator to duell meter house. 2-3" flowlines from meter house merging into 1-4" flowline to offsite dogleg. 2-1" flowlines from separator to pumpjack engine fuel gas.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	(1) on duell separator stack.		

Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Natural gas powered engines on both pumpjacks.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 215235 Type: WELL API Number: 067-06840 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 291757 Type: WELL API Number: 067-09384 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.
Gradient Terraces	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905280	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4886528