

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2019

Submitted Date:

07/22/2019

Document Number:

687905277

FIELD INSPECTION FORM

Loc ID 333432 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215245	WELL	PR	02/01/1987	GW	067-06850	CUGNINI A 1	PR
291008	WELL	PR	06/12/2007	GW	067-09375	CUGNINI A 3	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on sign at tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information posted on signs.	
Corrective Action:		Date: _____

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Low profile pumpjacks due to center pivot irrigation sprinkler that crosses location.		
Corrective Action:		Date:	
Type: Flow Line	# 13		
Comment:	2-3" flowlines from wellheads to separator. 2-2" flowlines from separator blowdown to produced water tank. 2-2" flowlines from separator dump valve to offsite gathering system. 2-2" flowlines from separator dump valve to produced water tank. 2-3" flowlines from separator to duell meter house. 2-3" flowlines from meter house merging into 1-4" flowline to offsite dogleg.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads.		

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric VFD driven motors on low profile pumpjacks with MCC.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On duell separator stack.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215245 Type: WELL API Number: 067-06850 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut-in for maintenance according to LOTO.

Corrective Action: _____ Date: _____

Facility ID: 291008 Type: WELL API Number: 067-09375 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Ditches	Pass			
Gradient Terraces	Pass	Gravel	Pass			
Drains	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905287	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4886535