

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2019

Submitted Date:

07/22/2019

Document Number:

689703373**FIELD INSPECTION FORM**

Loc ID 334895 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259548	WELL	PR	06/05/2002	GW	045-07742	UNOCAL GM 246-1	PR
275226	WELL	PR	07/27/2005	GW	045-13475	WILLIAMS GM 542-1	PR
275227	WELL	PR	07/27/2005	GW	045-13474	WILLIAMS GM 442-1	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 07/22/2019 at approximately 1330 hours, I, Inspector Mike Longworth, conducted a producing wells field inspection at Terra UNOCAL GM 246-1, at Location # 334895 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Seals laying behind separators.

Comply with Rule 603.f.

C.A. Date 08/02/2019

Ditch around separators has been washed out and sediment build up. Uncontrolled flow has created erosion of checkdam. Ruts in front of separators.

Install or repair required BMPs per Rule 1002.f.

C.A. Date 08/23/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Seals laying behind separators.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/02/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Heated Separator	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>259548</u>	Type: <u>WELL</u>	API Number: <u>045-07742</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>275226</u>	Type: <u>WELL</u>	API Number: <u>045-13475</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>275227</u>	Type: <u>WELL</u>	API Number: <u>045-13474</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail					

Comment: Ditch around separators has been washed out and sediment build up. Uncontrolled flow has created erosion of checkdam. Ruts in front of separators.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/23/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703374	Inspection 689703373 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4887025">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4887025</a>