

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2019

Submitted Date:

07/23/2019

Document Number:

680305311

**FIELD INSPECTION FORM**

Loc ID: 312139 Inspector Name: SCHURE, KYM On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 35190  
Name of Operator: GRAYHORSE OPERATING INC  
Address: 20 EAST 5TH ST STE 320  
City: TULSA State: OK Zip: 74103

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone         | Email                   | Comment |
|---------------|---------------|-------------------------|---------|
| Koehler, Bob  |               | bob.koehler@state.co.us |         |
| Crumley, Tim  | (970)768-5659 | tcrumley@centurytel.net |         |
| Crumley, Judy |               | jlccrumley@gmail.com    |         |
| Burn, Diana   |               | diana.burn@state.co.us  |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 218811      | WELL | IJ     | 05/01/2000  | DSPW       | 075-05562 | HOXIE 2 WD    | SI          |

**General Comment:**

WO - IJ well repair to restore mechanical integrity Doc#680305106 dated 06/10/2019. Operator has determined setting a liner for repair.

**Location**

|                    |                                    |       |  |
|--------------------|------------------------------------|-------|--|
| <b>Lease Road:</b> |                                    |       |  |
| Type               | Access                             |       |  |
| comment:           | Two track across dryland cropland. |       |  |
| Corrective Action: |                                    | Date: |  |

Overall Good:

|                      |              |       |  |
|----------------------|--------------|-------|--|
| <b>Signs/Marker:</b> |              |       |  |
| Type                 | WELLHEAD     |       |  |
| Comment:             | Satisfactory |       |  |
| Corrective Action:   |              | Date: |  |

|                                  |              |       |  |
|----------------------------------|--------------|-------|--|
| <b>Emergency Contact Number:</b> |              |       |  |
| Comment:                         | Satisfactory |       |  |
| Corrective Action:               |              | Date: |  |

Overall Good:

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |                            |       |  |
|--------------------|----------------------------|-------|--|
| <b>Fencing/:</b>   |                            |       |  |
| Type               | WELLHEAD                   |       |  |
| Comment:           | Heavy welded wire surround |       |  |
| Corrective Action: |                            | Date: |  |

|                    |                                    |       |                 |
|--------------------|------------------------------------|-------|-----------------|
| <b>Equipment:</b>  |                                    |       | corrective date |
| Type: Other        | # 0                                |       |                 |
| Comment:           | No change in equipment inventoried |       |                 |
| Corrective Action: |                                    | Date: |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Venting:</b>    |  |       |  |
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 218811 Type: WELL API Number: 075-05562 Status: IJ Insp. Status: SI

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 06/11/2014

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: [WO in process to restore mechanical integrity per Doc#680305106. Setting liner for repairs.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: [RU for liner, weld collars on the first \(10\) jts of liner pipe, tagged plug, RU pump and pump \(25\) bbls. slurry, shut well in, shut down for night.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | In Process      | Other                   | In Process            |               |                          |         |

Comment: [Located within dryland cropland with rotational tillage](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <a href="#">WO in process for repairs to restore mechanical integrity in IJ well.</a> | schureky | 07/23/2019 |