

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2019

Submitted Date:

07/22/2019

Document Number:

685101414

FIELD INSPECTION FORM

Loc ID 431789 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431787	WELL	PR	10/12/2013	OW	123-36774	IONE 1B-10H	PR
431788	WELL	PR	10/19/2013	OW	123-36775	IONE 1E-10H	PR
431790	WELL	PR	10/09/2013	OW	123-36776	IONE 1D-10H	PR
431791	WELL	PR	10/09/2013	OW	123-36777	IONE 1F-10H	PR
431792	WELL	PR	10/09/2013	OW	123-36778	IONE 1C-10H	PR
431793	WELL	PR	10/12/2013	OW	123-36779	IONE 1A-10H	PR
431794	WELL	PR	10/09/2013	OW	123-36780	IONE 1G-10H	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: 6' Hog Fence

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment # 7

Comment: Automatioon

Corrective Action:

Date: _____

Type: Bradenhead # 7

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift # 7

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 431787 Type: WELL API Number: 123-36774 Status: PR Insp. Status: PR

Facility ID: 431788 Type: WELL API Number: 123-36775 Status: PR Insp. Status: PR

Facility ID: 431790 Type: WELL API Number: 123-36776 Status: PR Insp. Status: PR

Facility ID: 431791 Type: WELL API Number: 123-36777 Status: PR Insp. Status: PR

Facility ID: 431792 Type: WELL API Number: 123-36778 Status: PR Insp. Status: PR

Facility ID: 431793 Type: WELL API Number: 123-36779 Status: PR Insp. Status: PR

Facility ID: 431794 Type: WELL API Number: 123-36780 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	07/22/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101415	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4887022