

# Interim Reclamation and Stormwater Inspection

July 22, 2019

Operator: EXTRACTION OIL & GAS INC #10459

Location ID: 450197

Inspection Document #: 697500365

Larimer County, CO

NESE Section 26 T5N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 1.** Photo taken along a portion of the access road, facing North. Photo illustrates the Operator has seeded and straw crimped mulch throughout the interim areas. Also, Operator has installed rip-rap as check dams along the access road ditch. BMP maintenance is required along a section where truck traffic damaged the BMPs.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 2.** Photo taken from the southeastern interim area, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 3.** Photo taken from the western interim reclamation area, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the western interim reclamation area, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 5.** Photo taken from the northwestern well pad, facing South. Photo illustrates a ditch BMP that is directed to a stabilized outlet. It appears the Operator is in-process of installing rip-rap along the ditch BMP.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 6.** Photo taken from the northwestern well pad, facing East. See comments under Photo 5.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 7.** Photo taken from the northwestern perimeter of location, facing West. Photo illustrates a ditch and berm BMP that has been installed in conjunction with a stabilized outlet. Portions of the berm BMP have been stabilized with erosion control blankets.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 8.** Photo taken from the northwestern perimeter of location, facing East. See comments under Photo 7.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 9.** Photo taken from the northeastern perimeter of location, facing North. Photo illustrates a stabilized outlet.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 10.** Photo taken from the northeastern perimeter of location, facing East. Photo illustrates a stabilized outlet area of the culvert.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 11.** Photo taken from the northeastern perimeter of location, facing South. Photo illustrates a stabilized channel (in-process) that is directed to a stabilized outlet.

Inspection Photos  
Location Name: McGirr /26-L  
Location ID: 450197



**Photo 12.** Photo taken from the northeastern well pad, facing East. Photo illustrates an inlet area that is in-process of being stabilized with rip-rap.