

## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 327361




**Photo #1**

**Sooner Unit 6-21 (05-123-14562) Wellsite**

**Bradenhead NOT plumbed to surface**

**Stained soil**

*previous insp.*



**Photo #2**

**Sooner Unit 6-21 Wellsite**

**Bradenhead NOW plumbed to surface**

**Stained soil - Remains**

## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



**Photo #3**  
**Sooner Unit 6-21** Wellsite  
**Pumpjack ( North, South sides )**  
**Stained soil**  
*previous insp.*



**Photo #4**  
**Sooner Unit 6-21** Wellsite  
**Pumpjack ( North, South sides )**  
**Stained soil - Remains**



## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SEnw

**Location #:** 327361



**Photo #5**

**Sooner Unit** Produced H<sub>2</sub>O tanks

*Debris near East produced H<sub>2</sub>O tanks remains  
previous insp.*



**Photo #6**

**Sooner Unit** Produced H<sub>2</sub>O tanks

*Debris near East produced H<sub>2</sub>O tanks  
NOW removed*

## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SEnw

Location #: 327361



**Photo #7**

**Sooner Unit** Produced H2O tank room

*Debris near middle West produced H2O tank  
previous insp.*



**Photo #8**

**Sooner Unit** Produced H2O tank room

**Debris near middle West produced H2O tank  
NOW appears removed**



## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



**Photo #9**

**Sooner Unit** Produced H2O tank room

*Debris near middle East produced H2O tank  
previous insp.*



**Photo #10**

**Sooner Unit** Produced H2O tank room

**Debris near middle East produced H2O tank  
NOW appears removed**

## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 327361



**Photo #11**

**Sooner Unit** North treater shed

**Unused equipment**

*previous insp.*



**Photo #12**

**Sooner Unit** North treater shed

**Unused equipment – Removed**  
**Stained soil – Appears mitigated**



## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



**Photo #13**

**Sooner Unit** North treater shed

**Unused equipment - outside**

*previous insp.*



**Photo #14**

**Sooner Unit** North treater shed

**Unused equipment outside – Removed**

## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



Colorado Oil & Gas Conservation Commission  
40.65192, -103.86979, 1420.0m, 26°  
2018/09/18 03:22:30 PM

**Photo #15**

**Sooner Unit** Produced H2O tank room – E. door

***Unused equipment***  
*previous insp.*



Colorado Oil & Gas Conservation Commission  
40.65192, -103.86986, 1448.0m, 36°  
07/22/2019 04:02:53 PM

**Photo #16**

**Sooner Unit** Produced H2O tank room – E. door

***Unused equipment - Removed***



## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



**Photo #17**

**Sooner Unit** North Treater

*Stained soil and previously leaking equip.  
previous insp.*



**Photo #18**

**Sooner Unit** North Treater

*Stained soil and previously leaking equip.  
Appears mitigated*

## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 327361



**Photo #19**

**Sooner Unit** South Treater shed

**Stained soil**

*previous insp.*



**Photo #20**

**Sooner Unit** South Treater shed

**Treater Removed - Stained soil**

***Appears mitigated***



## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SEnw

**Location #:** 327361



**Photo #21**

**Sooner Unit** Crude oil recycle pump

***Stained soil***

*previous insp.*



**Photo #22**

**Sooner Unit** Crude oil recycle pump

**Stained soil**

***Appears mitigated***

## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



**Photo #23**

**Sooner Unit** Produced H<sub>2</sub>O tanks N side.

**Stained soil**

*previous insp.*



**Photo #24**

**Sooner Unit** Produced H<sub>2</sub>O tanks N side.

**Stained soil**

*Appears mitigated*



## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SEnw

Location #: 327361



**Photo #25**

**Sooner Unit** Produced H<sub>2</sub>O transfer pumps | tank

**Stained soil**

*previous insp.*



**Photo #26**

**Sooner Unit** Produced H<sub>2</sub>O transfer pumps | tank

**Removed | Stained soil**

***Appears mitigated***

## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SENW

**Location #:** 327361



**Photo #27**

**Sooner Unit** Crude Oil tanks - loadout

**Stained soil**

*previous insp.*



**Photo #28**

**Sooner Unit** Crude Oil tanks - loadout

**Stained soil**

*Appears mitigated*



## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SEnw

**Location #:** 327361



**Photo #29**  
**Sooner Unit** Crude Oil tanks - drainline  
**Stained soil**  
*previous insp.*



**Photo #30**  
**Sooner Unit** Crude Oil tanks - drainline  
**Stained soil**  
*Appears mitigated*

## Inspection Photos

**Location Name:** SOONER UNIT-68N58W /21SEnw

**Location #:** 327361



**Photo #31**

**Sooner Unit** Injection Pump – N side

***Stained floor***

*previous insp.*



**Photo #32**

**Sooner** Injection Pump – N side

***Stained floor - Remains***



## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SEnw

Location #: 327361



**Photo #33**

**Sooner Unit** Injection Pump – S side

***Stained floor***

*previous insp.*



**Photo #34**

**Sooner** Injection Pump – S side

***Stained floor - Remains***



## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 327361



**Photo #35**

**Sooner Unit H2O pit – skim**

***Culvert Rusted***

*previous insp.*



**Photo #36**

**Sooner H2O pit – skim**

***Culvert Rusted***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 327361



**Photo #37**

**Sooner Unit H2O pit – skim**

***Steel tank – NO Capacity posted***



**Photo #38**

**Sooner Unit H2O pit**

***Weeds***

## Inspection Photos

Location Name: SOONER UNIT-68N58W /21SENW

Location #: 327361



Colorado Oil & Gas Conservation Commission  
40.65164, -103.87037, 1417.0m, 41°  
07/22/2019 05:29:03 PM

**Photo #39**

**Sooner Unit Battery | Facility**



Colorado Oil & Gas Conservation Commission  
40.65196, -103.87016, 1419.0m, 100°  
07/22/2019 05:27:06 PM

**Photo #40**

**Sooner Unit Battery | Facility**

**Signs**