

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2019

Submitted Date:

07/23/2019

Document Number:

687905296**FIELD INSPECTION FORM**

Loc ID 333620 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215815	WELL	PR	01/17/1990	GW	067-07420	SIMON LAND & CATTLE 21U-1R 1	PR
294771	WELL	PR	08/12/2008	GW	067-09500	SIMON LAND & CATTLE 21U-1R 3	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on sign at tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Location sign appears to be missing. Could not find it at entrance, on-site, on lease road or at gate.		
Corrective Action:	Install sign at location to comply with Rule 210.	Date:	08/23/2019

Emergency Contact Number:

Comment:	Contact information is missing due to sign missing from location.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Cattle panels around wellheads and pumpjacks		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separators, meter houses, and produced water tank.		
Corrective Action:		Date:	

Equipment:

Type: Vertical Heated Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric VFD drive motors on pumpjacks with MCC.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:	On duell separator stack.		Date:	
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:	12" pig launcher on edge of location.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	PVC bradenhead access.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 12			
Comment:	2-3" flowlines from wellheads to separators. 2-2" flowlines from spearator blowdowns to produced water tank. 2-2" flowlines from separator dump valves to offsite produced water gathering system. 2-2" flowlines from separator dump valves to produced water tank. 2-3" flowlines from separators to meter houses. 2-4" flowlines from meter houses to offsite dogleg.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected FacilitiesFacility ID: 215815 Type: WELL API Number: 067-07420 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 294771 Type: WELL API Number: 067-09500 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Ditches	Pass	Ditches	Pass			
Gradient Terraces	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905305	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4888026
687905306	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4888027