

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2019

Submitted Date:

07/23/2019

Document Number:

687905291

FIELD INSPECTION FORM

Loc ID 334267 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215348	WELL	PR	07/07/1989	GW	067-06953	SIMON LAND & CATTLE 22-01 1	PR
294382	WELL	PR	01/14/2008	GW	067-09485	SIMON LAND & CATTLE 22-01 3	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at entrance of location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on sign at tank.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on signs.		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator, meterhouses and produced water tank.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		

Comment:	Electric VFD drive motors on pumpjack and LRP with MCC		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Wellheads.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 13			
Comment:	2-3" flowlines from wellheads to separators. 2-2" flowlines form separator blowdowns to produced water tank. 2-2" flowlines from separator dump valves to offsite gathering system. 2-2" flowlines from separator dump valves to produced water tank. 2-3" flowlines from separator to meter house. 2-3" flowlines from meter house to 1-4" common header to offsite dogleg.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 2			
Comment:	Pumpjack and LRP.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:	
Comment:			Date:
Corrective Action:			Date:

Flaring:

Type		Date:	
Comment:			Date:
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215348 Type: WELL API Number: 067-06953 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 294382 Type: WELL API Number: 067-09485 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					
Ditches	Pass	Gravel	Pass			
Gravel	Pass					
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905300	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4888021