

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/17/2019

Document Number:

689901009**FIELD INSPECTION FORM**Loc ID 312069 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ronaldmack@tcenergy.us	
,		ediefitzgerald@tcenergy.us	
		robfooss@tcenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262544	WELL	PR	01/01/2019	GW	071-07561	APACHE CANYON 08-02R	RI

**General Comment:**

Location inspection.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	There is road damage, rutting, and potholes along the main road.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	08/16/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type			
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

**Good Housekeeping:**

Type	STORAGE OF SUPL			
Comment:	There is batteries and various other supplies at the engine skid.			
Corrective Action:	Remove supplies and trash. Comply with Rule 603.f .		Date:	08/16/2019
Type	OTHER			
Comment:	There is oily waste in the engine skid.			
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	08/16/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	There is a dripping water leak at the wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.			Date: 07/19/2019

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402112727	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881635</a>
689901010	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881634</a>