

Inspection Photos

API#045-19727

Operator: URSA

Inspection Number: 692401191

Inspection Date: 6/24/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

June 24, 2019



Photo#2:
Anchors remain on site.



Photo#3:
Debris on site.

June 24, 2019



Photo#4:
Scotch thistle, Noxious Weed on site.



Photo#5:
Scotch thistle, Noxious Weed on site.

June 24, 2019



Photo#6:
Slopes and pad perimeters have heavy establishment of ruderal weeds.



Photo#7:
Slopes and pad perimeters have heavy establishment of ruderal weeds.

June 24, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa PA Porter API#045-19727



Photo#8:
Fill slope has areas of spotty establishment of desirable vegetation.



Photo#9:
Fill slope has areas of spotty establishment of desirable vegetation.

June 24, 2019



Photo#10:
Fill slope has areas of spotty establishment of desirable vegetation.



Photo#11:
Fill slope has areas of spotty establishment of desirable vegetation.

June 24, 2019



Photo#12:
Cut slope has spotty establishment of desirable
vegetation.



Photo#13:
Slopes and pad perimeters have heavy
establishment of ruderal weeds.

June 24, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa PA Porter API#045-19727



Photo#14:
North fill slope has good establishment of desirable vegetation.

June 24, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa PA Porter API#045-19727