

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

680305319**FIELD INSPECTION FORM**Loc ID 312139 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 35190Name of Operator: GRAYHORSE OPERATING INCAddress: 20 EAST 5TH ST STE 320City: TULSA State: OK Zip: 74103**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Koehler, Bob		bob.koehler@state.co.us	
,		kyancey@grayhorse.net	
Burn, Diana		diana.burn@state.co.us	
Ellis, Charles		caellis@grayhorse.net	
Quint, Craig		craig.quint@state.co.us	
Crumley, Judy		jlcrcumley@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218811	WELL	IJ	05/01/2000	DSPW	075-05562	HOXIE 2 WD	SI

General Comment:

UIC/MIT 2019 - Repairs completed (set liner). MIT performed on 06/10/2019 Doc#680305106 (failed). Last UIC/MIT dated 06/11/2014.

NOTE TO OPERATOR: Please submit Form 21 via COGCC e-form.

Form 42 Doc# 402119134 received

Form 21 copy attached

Reference: FIR Doc# 680305319 on e-form Form 21 submission.

Location

Lease Road:			
Type	Access		
comment:	Two track dryland cropland		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Satisfactory

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Heavy welded wire surround		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 218811 Type: WELL API Number: 075-05562 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>JSND</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>06/11/2014</u>
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: 0 Csg psi: 370 BH psi: _____Insp. Status: PassComment: Repairs: Set liner - restored mechanical integrity - SATISFACTORY
Pressure held @ (370)psi. throughout duration of (15) min. test
Well is approved to return to IJ service.
Form 21 copy attached.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Located within dryland cropland with rotational tillage.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
UIC/MIT 2019 - Repairs completed per Doc#680305106. SATISFACTORY	schureky	07/24/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680305321	Form 21 copy	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4888865