

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2019

Submitted Date:

07/24/2019

Document Number:

698600101

FIELD INSPECTION FORM

Loc ID 320129 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 90615
Name of Operator: TUDEX PETROLEUM INC
Address: 2121 39TH AVE NE UNIT E
City: CALGARY State: AL Zip: T2E 6R7

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202757	WELL	PR	07/31/2008	OW	001-08162	CROFF 12-5	TA

General Comment:

This is an orphaned well inspection. Inspection completed as site visit prior to plug and abandonment task and verify landowner identified possible flowline riser for removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Location			
Lease Road:			
Type	Access		
comment:	Dirt and gravel road off maintained county road.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	COGCC contact sticker.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Chain link fencing topped with barb wire.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	2" steel flow line with valve across access road from wellhead.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202757 Type: WELL API Number: 001-08162 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is an Orphaned Well Program well. Valves at wellhead are closed and outlets bull plugged. Production equipment decommissioning and removal previously completed.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
The Tudex Plugging and Flow line Abandonment Project is underway. The Croff 12-5 is one of the wells on the project to be plugged and abandoned. This site visit was completed in preparation for moving rig onto the well location for plugging task and to locate flow line riser identified by landowner and requested removal. The flow line riser was located and is across access road from well site. Landowner has placed a black plastic culvert over T-Post marking location. The flow line is 2" line with baylon valve installed but is open ended. No issues were noted at time of inspection that would prevent rig and equipment from staging and performing plugging task.	stjohnw	07/24/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600102	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889079