

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

679601211**FIELD INSPECTION FORM**Loc ID 432771 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspections@srcenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432770	WELL	PR	03/01/2018	GW	123-37276	Renfroee 32-1-36CHZ	SI
432772	WELL	PR	03/01/2018	OW	123-37277	Renfroee 32-1-36NHZ	SI
432811	WELL	PR	03/01/2018	GW	123-37292	Renfroee 42-1-36NHZ	SI
432812	WELL	PR	03/01/2018	GW	123-37293	Renfroee C-1-36NHZ	SI
432813	WELL	PR	07/01/2018	GW	123-37294	Renfroee 42-1-36CHZ	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x5)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	SE water tank needs NFPA label replaced. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/24/2019
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash inside berm that contains separators. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	08/03/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused riser. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	08/24/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	

Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	10	300 BBLS	STEEL AST		40.517600,-104.720500	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berm is lined					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 432770 Type: WELL API Number: 123-37276 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. No production records in COGCC data base since MAY 2019

Corrective Action: _____ Date: _____

Facility ID: 432772 Type: WELL API Number: 123-37277 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. No production records in COGCC data base since MAY 2019.

Corrective Action: _____ Date: _____

Facility ID: 432811 Type: WELL API Number: 123-37292 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. No production recods in COGCC data base since MAY 2019.

Corrective Action: _____ Date: _____

Facility ID: 432812 Type: WELL API Number: 123-37293 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. No production records in COGCC data base since MAY 2019.

Corrective Action: _____ Date: _____

Facility ID: 432813 Type: WELL API Number: 123-37294 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. No production records in COGCC data base since MAY 2019.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Soil sunken in, forming hole near compressor. See attached photo.
 Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/24/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday, July 24, 2019 at approximately 13:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at RENFROE PAD (SRC Energy), at location #: 432771 in WELD COUNTY Colorado.</p> <p>While there, I observed a shut in location.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. NFPA placard appears to have been peeled off a produced water tank. Needs to be replaced. INSTALL SIGN TO COMPLY WITH RULE 210.D. (Corrective Action Date: August 24, 2019) See attached photo #3. 2. Unused riser near other ECDs. COMPLY WITH RULE 603.F. (Corrective Action Date: August 24, 2019) See attached photo #4. 3. Trash near west separators in berm. COMPLY WITH RULE 603.F. (Corrective Action Date: August 3, 2019) See attached photos #6, 8. 4. Erosion/soil appears to be sinking (beginning to create a hole) east side of compressor. INSTALL OR REPAIR REQUIRED BMPs PER RULE 1002.F. (Corrective Action Date: August 24, 2019) See attached photo #10. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	07/24/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601212	Renfroe 32-1-36CHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889695
679601213	Renfroe 32-1-36NHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889696
679601214	Renfroe 42-1-36CHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889697
679601215	Renfroe 42-1-36NHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889698
679601216	Renfroe C-1-36NHZ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889699
679601217	Renfroe PAD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889700