

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

679704867**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 314341      Moran, Rick      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10556Name of Operator: PLUG NICKEL OIL COMPANY INCAddress: 2552 NORTH 500 EASTCity: VERNAL      State: UT      Zip: 84078**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                      | Comment |
|------------------|--------------|----------------------------|---------|
| Mortensen, Danny | 435-790-4709 | hogue@stratanet.com        |         |
| Kellerby, Shaun  | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228455      | WELL | SI     | 10/01/2018  | OW         | 103-05309 | MURPHY A-2    | SI          |

**General Comment:**COGCC Inspection Report Summary.On 7-24-2019 at approximately 17:30, inspector Rick Moran, conducted a routine inspection at Plug Nickel Oil well Murphy A-2 in Rio Blanco county.During this inspection the following compliance issues were observed:

- 1) Weeds next to pump jack. Photo 2. Complete by 8-16-2019.
- 2) Battery sign missing "911" and emergency contact label peeling off. Photo 3. Complete by 9-23-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.This is a summary of inspection report 679704867.

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | WELLHEAD  |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | TANK LABELS/PLACARDS  |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY   |       |            |
| Comment:             | Battery sign missing "911" and emergency contact label is peeling off sign. |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.b.                                     | Date: | 09/23/2019 |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                          |       |            |
|--------------------|--------------------------|-------|------------|
| Type               | WEEDS                    |       |            |
| Comment:           | Weeds next to pump jack. |       |            |
| Corrective Action: | Comply with Rule 603.f . | Date: | 08/16/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
| <b>Equipment:</b>        |     |       | corrective date |
| Type: Pump Jack          | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Deadman # & Marked | # 3 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |                       |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
| CRUDE OIL          | 1 | 200 BBLS | STEEL AST |         | 40.069300,-108.774600 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   | Date:    |           |         |                       |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 228455 Type: WELL API Number: 103-05309 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production September 2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 679704868    | inspection photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889810">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889810</a> |