

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused risers near horizontal separator. See attached photo.		
Corrective Action:	Comply with rule 603.f.		Date: <u>08/25/2019</u>
Type	OTHER		
Comment:	Stained soil in separator house. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>08/25/2019</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.510500,-104.756200
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday, July 25, 2019 at approximately 11:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at MESBERGEN 45-3D BATTERY (SRC Engery), at location #: 302583 in WELD COUNTY Colorado. While there, I observed a shut in tank battery. During this inspection the following possible compliance issues were observed: 1. Multiple unused risers near the horizontal separator. COMPLY WITH RULE 603.F. (Corrective Action Date: August 25, 2019) See attached photo #2. 2. Stained soil in separator house. SECURELY FASTEN ALL VALVES, PIPES, AND FITTING TO ENSURE GOOD MECHANICAL CONDITION, INSPECT IN REGULAR INTERVALS AND MAINTAIN IN GOOD MECHANICAL CONDITIONS PER RULE 605.D. (Corrective Action Date: August 25, 2019) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	07/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601240	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4890239