

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2019

Submitted Date:

07/25/2019

Document Number:

679704880

FIELD INSPECTION FORM

Loc ID 315048 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 6720
Name of Operator: ROBERT L BAYLESS PRODUCER LLC
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230165	WELL	PR	05/01/2018	GW	103-07824	PHILADELPHIA CREEK 9	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 7-25-2019 at approximately 10:45, inspector Rick Moran, conducted a routine well inspection at Robert L Bayless well Philadelphia Creek 9 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679704880.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:			Date:

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 3				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 230165 Type: WELL API Number: 103-07824 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: _____ Lat: 39.906900 Long: -108.724100

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action Date: _____

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704881	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4890362