

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2019

Submitted Date:

07/26/2019

Document Number:

694900108**FIELD INSPECTION FORM**

Loc ID 432265	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432268	WELL	SI	07/01/2018	GW	045-21936	HMU 6-15A (J6SEB)	SI
432269	WELL	PR	05/20/2014	GW	045-21937	HMU 6-13AA (J6SEB)	PR
432272	WELL	PR	05/16/2014	GW	045-21938	HMU 6-11A (J6SEB)	PR
432277	WELL	PR	05/17/2014	GW	045-21939	HMU 6-12D (J6SEB)	PR
432280	WELL	PR	05/27/2014	GW	045-21940	HMU 6-15AA (J6SEB)	PR
432281	WELL	PR	05/14/2014	GW	045-21941	HMU 6-13A (J6SEB)	PR
432282	WELL	PR	05/17/2014	GW	045-21942	HMU 6-12DD (J6SEB)	PR
432283	WELL	PR	05/12/2014	GW	045-21943	HMU 6-13D (J6SEB)	PR
432284	WELL	SI	07/01/2018	GW	045-21944	HMU 6-15D (J6SEB)	SI

<b>General Comment:</b> <a href="#">Follow up inspection from document# 689301268</a>
--

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Stained Rock in Tank Battery containment, see photo

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.

Date: 07/11/2018

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator # 9

Comment:

Corrective Action:

Date:

Type: Other # 1

Comment: bear proof dumpster

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Pig Station # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 3

Comment: chemical tanks at well heads

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 10

Comment:

Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	1000 gallon tank				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:			Date:		

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**

Facility ID: 432268 Type: WELL API Number: 045-21936 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date:

Facility ID: 432269 Type: WELL API Number: 045-21937 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:  Date:

Facility ID: 432272 Type: WELL API Number: 045-21938 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:  Date:

Facility ID: 432277 Type: WELL API Number: 045-21939 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:  Date:

Facility ID: 432280 Type: WELL API Number: 045-21940 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:  Date:

Facility ID: 432281 Type: WELL API Number: 045-21941 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:  Date:

Facility ID: 432282 Type: WELL API Number: 045-21942 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:  Date:

Facility ID: 432283 Type: WELL API Number: 045-21943 Status: PR Insp. Status: PR

**Producing Well**Comment: [plunger lift](#)

Corrective Action:

Date:

Facility ID: 432284 Type: WELL API Number: 045-21944 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Compaction				
Rip Rap		Gravel				
Ditches						
Retention Ponds						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 7/26/19 at approximately 12:15 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus J6SEB Pad, at location # 432265 in Garfield County, Colorado.</p> <p>While there, I observed normal production operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>That the staining in the tank battery from the previous inspection document # 689301268 was still in place.</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	07/26/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900112	694900108	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892532">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892532</a>