

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/26/2019

Submitted Date:

07/26/2019

Document Number:

679704895**FIELD INSPECTION FORM**

Loc ID 335896	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 16 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100264</u> Name of Operator: <u>XTO ENERGY INC</u> Address: <u>110 W 7TH STREET</u> City: <u>FORTH WORTH</u> State: <u>TX</u> Zip: <u>76102</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295534	WELL	SI	04/01/2019	GW	103-11248	PICEANCE CREEK UNIT 296-5A1	SI
295535	WELL	PR	01/03/2012	GW	103-11247	PICEANCE CREEK UNIT 296-5A2	PR
295536	WELL	PR	01/02/2012	GW	103-11246	PICEANCE CREEK UNIT 296-5A3	PR
295537	WELL	PR	10/01/2018	GW	103-11245	PICEANCE CREEK UNIT 296-5A4	PR
295538	WELL	PR	12/31/2011	GW	103-11244	PICEANCE CREEK UNIT 296-5A5	PR
295539	WELL	PR	04/01/2017	GW	103-11243	PICEANCE CREEK UNIT 296-5A7	PR
295540	WELL	PR	12/28/2011	GW	103-11242	PICEANCE CREEK UNIT 296-5A8	PR
295541	WELL	PR	06/01/2017	GW	103-11241	PICEANCE CREEK UNIT 296-5A9	PR
295542	WELL	PR	12/30/2011	GW	103-11240	PICEANCE CREEK UNIT 296-5A6	PR
295543	WELL	PR	12/17/2011	GW	103-11239	PICEANCE CREEK UNIT 296-5A10	PR

General Comment:

COGCC Inspection Report Summary.

On 7-26-2019 at approximately 13:45, inspector Rick Moran, conducted a routine well inspection at pad Piceance Creek Unit 296 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679704895.

LocationOverall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Other	# 6		corrective date
Comment:	Equipment building, header, 4 trailers with equipment.		
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Three containers of MC MX 6-2719 and 1 container of MC MX 6-4767 all with secondary containment.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	In buidling.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 295534	Type: WELL	API Number: 103-11248	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Shut in.				
Corrective Action: _____				Date: _____
Facility ID: 295535	Type: WELL	API Number: 103-11247	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____
Facility ID: 295536	Type: WELL	API Number: 103-11246	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____
Facility ID: 295537	Type: WELL	API Number: 103-11245	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____
Facility ID: 295538	Type: WELL	API Number: 103-11244	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____
Facility ID: 295539	Type: WELL	API Number: 103-11243	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____
Facility ID: 295540	Type: WELL	API Number: 103-11242	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____
Facility ID: 295541	Type: WELL	API Number: 103-11241	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well on plunger lift.				
Corrective Action: _____				Date: _____

<u>Producing Well</u>			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	
Facility ID: 295542 Type: WELL API Number: 103-11240 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	
Facility ID: 295543 Type: WELL API Number: 103-11239 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704896	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892738