

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2019

Submitted Date:

07/26/2019

Document Number:

679704899

**FIELD INSPECTION FORM**

Loc ID 335877 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: 110 W 7TH STREET  
City: FORTH WORTH State: TX Zip: 76102

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	
Reid, Van		van_reid@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278492	WELL	PR	02/01/2018	GW	103-10604	PICEANCE CREEK UNIT T33X-29G1	PR
278580	WELL	PR	10/01/2013	GW	103-10607	PICEANCE CREEK UNIT T33X-29G2	PR
278582	WELL	PR	03/01/2017	GW	103-10606	PICEANCE CREEK UNIT T33X-29G3	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 7-26-2019 at approximately 15:00, inspector Rick Moran, conducted a routine well inspection at XTO Energy well Piceance Creek Unit T33X-29G1, G2, and G3 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679704899.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Other	# 1		
Comment:	Header.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	In building.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Container of MC MX 6-4767 with secondary containment.		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>278492</u>	Type: <u>WELL</u>	API Number: <u>103-10604</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Producing well on plunger lift.</u>		
Corrective Action:		Date:	
Facility ID: <u>278580</u>	Type: <u>WELL</u>	API Number: <u>103-10607</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Producing well on plunger lift.</u>		
Corrective Action:		Date:	
Facility ID: <u>278582</u>	Type: <u>WELL</u>	API Number: <u>103-10606</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Producing well on plunger lift.</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704900	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4892740</a>