

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/19/2019

Submitted Date:

07/22/2019

Document Number:

679704804**FIELD INSPECTION FORM**
 Loc ID 315412 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 82440Name of Operator: STEHLE OIL COMPANYAddress: P O BOX 1577City: CRAIG State: CO Zip: 81626**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Stehle, Cary	970-824-6909	carystehle@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230790	WELL	SI	11/01/2018	OW	103-08459	PINNACLE UNIT 10-30	SI

General Comment:

COGCC Inspection Report Summary.

On 7-19-2019 at approximately 13:45, inspector Rick Moran, conducted a follow up inspection at Stehle Oil Company well Pinnacle Unit 10 -30 in Rio Blanco county of FIR documents:

- 1) 685100516 dated 9-4-2018.
- 2) 689801591 dated 8-28-2018.
- 3) 685100500 dated 8-29-2018.
- 4) 673402283 dated 7-15-2015.
- 5) 673400952 dated 8-5-2014.

Complaint Form 18 documents:

- 1) 200446156 dated 8-19-2018.
- 2) 200446158 dated 8-20-2018.

The following compliance issues were identified as resolved:

- 1) Gas leak on yellow hose at well head.
- 2) Pit free board.

The following compliance issues were observed as uncompleted:

- 1) Tank label. Photo 5. Complete by 10-26-2018.
- 2) Battery sign. Photo 1. Complete by 10-26-2018.
- 3) Stained soil. Photos 7, 8, 9, 10, 11, 12, 13. Complete by 9-28-2018.
- 4) West tank bird stack screen. Photo 1. Complete by 9-28-2018.

Additional compliance issues were identified:

- 1) Open containers of oil. Photos 10, 11. Complete by 8-19-2019.
- 2) Oil saturated booms. Photo 6. Complete by 8-19-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679704804.

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign not posted.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/26/2018
Type	TANK LABELS/PLACARDS		
Comment:	Label is incomplete.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/26/2018

Emergency Contact Number:

Comment: 970-824-6909 or 970-629-1007

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open containers of oil next to tanks.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/19/2019
Type	DEBRIS		
Comment:	Oil saturated booms.		
Corrective Action:	Keep location free from trash and debris.	Date:	08/19/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil			
Comment:	Stained soil at: tank valves, well head, and pump jack exhaust.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.		Date: 09/28/2018

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Fence is partially folded down on east side.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:	No wildlife protection apparent on west tank stack.			
Corrective Action:	Install wildlife screen per Rule 605.b.(7).			Date: 09/28/2018
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Propane tank.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		40.201900,-107.083900
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 230790 Type: WELL API Number: 103-08459 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last recorded production October 2018.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat: <u>40.201765</u>	Long: <u>-107.084062</u>
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife Fencing Condition: _____

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402116710	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885421
679704805	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885416