

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2019

Submitted Date:

07/22/2019

Document Number:

692401182

FIELD INSPECTION FORM

Loc ID 463987 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Church, Matt	405-651-6853	mchurch@sandridgeenergy.com	
		sandridgeenvironmental@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463988	WELL	XX	04/16/2019		057-06623	PRU Alcorn 0880 1-10	CI

General Comment:

This is a Construction and Stormwater Inspection. Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 7/8/18. Conditions at time of Inspection were Clear Sunny Skies, at 75 degrees F with steady wind from the South. Elevation at Site is 8120 ft.

Location Construction

Location ID: 463987 CDP: _____

Comment: Work on Pad had been halted due to windy conditions and potential for fugitive dust. Topsoil has been salvaged; is stored at Northwest edge of location. Silt fence is installed as protective BMP for stockpile as well as perimeter control around site. Pad area has been graded and awaiting rocking operations. Immediate road into site had under matting laid and was being based and rocked at time of Inspection.

Corrective Action: _____ **Date:** _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: This Location is within a Sensitive Wildlife Habitat; Greater Sage Grouse and CPW Black Bear area.

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

DITCHES	Yes	Vehicle Trakcing	Yes`
---------	-----	------------------	------

Comments: Erosion BMPs: Culverts have been installed at HWY and location entries.

Other BMPs: Entry road off HWY 14 has been heavily graveled and rocked to function as tracking control. Some rock was being carried onto highway from big truck traffic. Contractors were keeping rock swept back to site.

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Corrective Action: _____ Date: _____

SILT FENCES	Yes		
-------------	-----	--	--

Comments: Erosion BMPs: Perimeter and access road silt fence has been overwhelmed and failed at points. One section of fence adjacent to stockpiled topsoil was not properly installed. Operator was aware of all failings, and said repairs were scheduled before end of day.

Other BMPs: _____

Corrective Action: Install sufficient/effective BMPs in accordance with, and monitoring per Good Engineering Practices per Rule 1002.f Date: 07/23/2019

Comment: Fugitive dust was observed. Light soil will be very susceptible to any traffic. Monitoring & controls will have to be implemented at all times Operator is conducting activities when windy conditions exist as indicated. Operator had water truck treating staging area while Inspector on site.

Corrective Action: Take actions to control fugitive dust per Rule 805.c **Date:** 07/23/2019

On Site Inspection (305):

Surface Owner Contact Information:
 Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:
 Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____
LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 463988 Type: WELL API Number: 057-06623 Status: XX Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402117679	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4886325
692401185	Inspection Photos CI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4886317