

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2019

Submitted Date:

07/29/2019

Document Number:

685101454

FIELD INSPECTION FORM

Loc ID 431712 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431710	WELL	PR	08/07/2013	OW	123-36749	MELBON 23N-8HZ	PR
431711	WELL	PR	08/07/2013	OW	123-36750	MELBON 23C-8HZ	PR
431718	WELL	PR	10/01/2017	OW	123-36754	MELBON 19N-E8HZ	PR
431719	WELL	SI	12/01/2018	OW	123-36755	MELBON 12N-8HZ	SI
431723	WELL	PR	08/01/2013	OW	123-36758	MELBON 12C-8HZ	PR
431726	WELL	PR	05/01/2015	OW	123-36760	MELBON 19N-W8HZ	PR
431756	WELL	PR	08/23/2013	OW	123-36765	MELBON 19C-8HZ	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment # 8

Comment: Automation and electric boxes

Corrective Action:

Date: _____

Type: Bradenhead # 4

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift # 4

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 431710 Type: WELL API Number: 123-36749 Status: PR Insp. Status: PR

Facility ID: 431711 Type: WELL API Number: 123-36750 Status: PR Insp. Status: PR

Facility ID: 431718 Type: WELL API Number: 123-36754 Status: PR Insp. Status: PR

Facility ID: 431719 Type: WELL API Number: 123-36755 Status: SI Insp. Status: SI

Facility ID: 431723 Type: WELL API Number: 123-36758 Status: PR Insp. Status: PR

Facility ID: 431726 Type: WELL API Number: 123-36760 Status: PR Insp. Status: PR

Facility ID: 431756 Type: WELL API Number: 123-36765 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	07/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101455	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4893946