

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2019

Submitted Date:

07/30/2019

Document Number:

689703411**FIELD INSPECTION FORM**Loc ID 426478 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426484	WELL	DG	03/04/2015	SI	045-21157	STORY GULCH 8502E-23	DG

**General Comment:****COGCC Inspection Report Summary**

On Monday 07/29/2019 at approximately 1200 hours, I, Inspector Mike Longworth, conducted a field inspection at Caerus SG L24 496, at Location # 426478 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Chemical container at wells is missing label.

Install sign to comply with Rule 210.d.

C.A. Date 09/30/2019

Cement cellar is not covered fully and rat hole has a void between casing and hole. An open casing between the 2nd and 3rd quadrant of wells.

Cover cellar and back fill around rat hole casing. Cover open casing between the 2nd and 3rd quadrant of wells.

C.A. Date 08/15/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical container at wells is missing label.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/30/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 426484 Type: WELL API Number: 045-21157 Status: DG Insp. Status: DG

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Surface casing drilled and set only. (Batch drilled)  
Cement cellar is not covered fully and rat hole has a void between casing and hole. An open casing between the 2nd and 3rd quadrant of wells.

Corrective Action: Cover cellar and back fill around rat hole casing. Cover open casing between the 2nd and 3rd quadrant of wells.

Date: 08/15/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703412	Inspection 689703411 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4894623">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4894623</a>