

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2019

Submitted Date:

07/30/2019

Document Number:

687905346

**FIELD INSPECTION FORM**

Loc ID 311912 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	<a href="#">All Inspections</a>
Inspections, All		inspections@catamountep.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216276	WELL	PR	02/09/1994	GW	067-07882	DAVIS GAS UNIT 2	PR
297206	WELL	PR	01/24/2018	GW	067-09603	IGW 150	PR

**General Comment:**

[Site inspection with photos at the end of this report.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank labels/placards posted on tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Contact information posted on signs. Missing 911. As of Jan. 1st 2019, a phone number at which the operator can be reached at all times; a phone number for local emergency services (911 where available) shall be required on all signs and tank batteries.

Corrective Action: Comply with Rule 210.d.

Date: 08/30/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 9		
Comment:	2-3" flowlines from wellheads to separators. 2-2" flowlines from separators to pumpjack engine fuel gas. 2-2" flowlines from separator dump valves to produced water tanks. 1-3" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg. 1-2" flowline from separator to offsite dogleg.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Wellheads.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Appears when new 2" fuel gas flowline was excavated for pumpjack, the ditch runs along north side, east to west of tank battery containment and the berm was compromised during construction. Livestock or wildlife may also be contributing to berm inadequacy.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 08/30/2019

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 216276 Type: WELL API Number: 067-07882 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing.

Corrective Action:

Date:

Facility ID: 297206 Type: WELL API Number: 067-09603 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Ditches	Pass	Gravel	Pass			
Gravel	Pass					
Compaction	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905352	Sign missing EMS# or 911	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4895674">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4895674</a>
687905353	Containment berm.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4895675">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4895675</a>