

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

07/30/2019

Document Number:

698100047

FIELD INSPECTION FORM

Loc ID 323972 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Pitt, Carmen		cpitt@vnrllc.com	Sr. EH&S
Fischer, Alex		alex.fischer@state.co.us	
Ghan, Scott		sghan@vnrllc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466240	SPILL OR RELEASE	AC			-	Gibson Gulch Unit-66S91W/29SWSW 323972	EI

General Comment:

COGCC Environmental Inspection conducted by EPS staff S. Arauza and J. Heil. Follow-up to operator's Spill/Release Report (Initial), doc #402118254.

Operator's Spill/Release Report documents a spill of condensate into an unlined, earthen secondary containment berm that was discovered on 7/22/2019. During field inspection, operator indicated that the estimated volume of condensate released from the subject tank was ~8.3 bbls. Operator's environmental contractor was on site guiding dig and haul of impacted soil on inspection date. See photos.

Per Rule 906.b, a Supplemental eForm 19 Spill/Release Report is due within ten calendar days of spill discovery date (7/22/2019). Operator shall repair or install berms or other secondary containment devices per Rule 605.a.(4) prior to resuming production to the impacted tank battery.

Inspected Facilities

Facility ID: 466240 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698100052	20190724 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4895682