

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2019

Submitted Date:

07/30/2019

Document Number:

696300377**FIELD INSPECTION FORM**
 Loc ID 423916 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10671Name of Operator: EDGE ENERGY II LLCAddress: 1301 WASHINGTON AVE SUITE 300City: GOLDEN State: CO Zip: 80401-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Turner, Ben		bturner@edgeenergy1.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423923	WELL	PR	11/29/2012	OW	123-33796	OWL CREEK 8-64-6 1H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds are actively growing on entire location, See photos		
Corrective Action:	Comply with Rule 603.f .	Date:	08/30/2019
Type	OTHER		
Comment:	Stained Soil at wellhead, See photo #3		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	08/30/2019
Type	OTHER		
Comment:	Wellhead appears to be leaking, See photo #3		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/30/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		40.694170,-104.598990
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: PETRIE, ERICA

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 423923 Type: WELL API Number: 123-33796 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 07/24/2019 approximately 11:37 AM, I, Inspector Erica Petrie, conducted a Field Inspection at Owl Creek 8-64-6 1H; Edge Energy II LLC, at Location #423916 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Wellhead appears to be leaking, see photo 3, Comply with Rule 605.d, Corrective Action date of 08.30.2019</p> <p>Stained Soil at wellhead, see photo 3, Comply with Rule 907.e, Corrective Action date of 08.30.2019</p> <p>Weeds actively growing around the entire location, see photos, Corrective Action date of 08.30.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Educational Inspection.</p>	petrie	07/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300378	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4895823