

Laramie Energy LLC  
API # 05-077-09476  
Inspection # 696600412



Battery sign at entrance to location

Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



Photo #1 Photo at entrance of location .



Photo #2 Photo at entrance of location



Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



Photo #3 Photo of tank battery.



Photo #4 photo at wellheads.

Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



**Photo #5 Erosion is evident along un-stabilized slope on the east side of location. Vegetation is choked out**



**Photo #6 Erosion is evident along un-stabilized slope on the east side of location. Vegetation is choked out. Berms around location, have been constructed as storm water BMP, with no stabilization.**



Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



**Photo #8 Erosion is evident along un-stabilized slope on the north side of location. Vegetation is choked out**



**Photo #9 Erosion is evident along un-stabilized slope on the north side of location. . Vegetation is choked out**

Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



**Photo #10 Berms around location, have been constructed as storm water BMP, with no stabilization.**



**Photo #11 Berms around location, have been constructed as storm water BMP, with no stabilization.**



Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



**Photo #12. Erosion from berm is moving down west and south slope choking vegetation. See photos**



**Photo #13 Erosion from berm is moving down west and south slope choking vegetation. See photos**



Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



**Photo #14. Sediment trap and drain on south side of location located by meter run, is in need of maintenance.**



**Photo #15. Sediment trap and drain on south side of location located by meter run is in need of maintenance.**



Caerus Piceance LLC  
API # 05-077-10163  
Inspection # 696600410



**Photo #16. Culvert by tank battery, is in need of maintenance.**



**Photo #17. Culvert by tank battery, is in need of maintenance.**