

Inspection Photos

API: 05-073-06368

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 7/25/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 1. Facing north at the beginning of the two track access road leading to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 3. Facing west toward the southern portion of the location. Vegetation is well established at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 4. Facing west at the center of the location. This area has predominately undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 5. Facing southeast at the center of the location. This area does not have adequate vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 6. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 7. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019

Inspection Photos



Photo 8. Facing west toward the southern portion of the location. Vegetation is well established at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06368 | Date: 7/25/2019