



Eck 12-90-1 #1—API—051-06107 - Inspection Doc 693900458-6/18/19
CA #1 of 2—Remove and properly store unused equipment and debris
All Debris Removed





Eck 12-90-1 #1—API—051-06107—Inspection Doc 693900458-6/18/19

CA #2 of 2—Slope Stabilization

Blankets decomposing at 18-months, as designed. Vegetation growth increased ~20% and still progressing



Eck 12-90-1 #1—API—051-06107—Inspection Doc 693900458-6/18/19

CA #2 of 2— Access Road Erosion, cut slopes, culvert and rock check dams

Access road ditch re-graded; vegetation stabilization progressing

Rock Check Dams and culverts maintained; more added