

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402101088

Date Received:

07/31/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10506

Name of Operator: SEELEY OIL COMPANY LLC

Address: PO BOX 9015

City: SALT LAKE State: UT Zip: 84109

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------------------|-------|---------------------------------|
| <u>Seeley, Nathaniel</u> | | <u>nathaniel@seeleyoil.com</u> |
| <u>Fischer, Alex</u> | | <u>alex.fischer@state.co.us</u> |
| <u>Heil, John</u> | | <u>john.heil@state.co.us</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800526

Inspection Date: 05/23/2019

FIR Submit Date: 05/24/2019

FIR Status: _____

Inspected Operator Information:

Company Name: QEP ENERGY COMPANY

Company Number: 10343

Address: 1050 17TH STREET - SUITE 800

City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 322118

Location Name: SOUTHEAST SPARGO- N38N20W Number: 1SESE County: DOLORES

Qtrqtr: SESE Sec: 1 Twp: 38N Range: 20W Meridian: N

Latitude: 37.578300 Longitude: -108.997400

FACILITY - API Number: 05-033-00 Facility ID: 209013

Facility Name: SOUTHEAST SPARGO Number: 1

Qtrqtr: SESE Sec: 1 Twp: 38N Range: 20W Meridian: N

Latitude: 37.578300 Longitude: -108.997400

CORRECTIVE ACTIONS:

1 CA# 125576

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 06/24/2019

Response: CA COMPLETED

Date of Completion: 06/22/2019

Concrete pad was pressure washed. Soil was removed and disposed of.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 125577

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 06/24/2019

Response: CA COMPLETED

Date of Completion: 06/22/2019

Operator
Comment: Soil was removed and disposed of.

COGCC Decision:

COGCC
Representative:

3 CA# 125578

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 05/25/2019

Response: CA COMPLETED

Date of Completion: 05/25/2019

Operator
Comment: This is a containment vessel underneath a vent line manifold. It had filled with rain and snow melt. The vessel was emptied on 5/25/2019 with a vacuum truck. On 6/22/2019 the area was inspected for staining and none was found.

COGCC Decision:

COGCC
Representative:

4 CA# 125579

Corrective Action: Install sign to comply with Rule 210.d.

Date: 07/24/2019

Response: CA COMPLETED

Date of Completion: 07/22/2019

Operator
Comment: Tank was labeled with capacity.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nathaniel Seeley

Signed: _____

Title: VP

Date: 7/31/2019 12:07:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|-----------------------|
| 402101123 | compressor 1 |
| 402101127 | compressor 2 |
| 402101130 | cement pad / soil 1 |
| 402101135 | cement pad / soil 2 |
| 402101137 | vent containment |
| 402129224 | capacity on vent tank |

Total Attach: 6 Files