

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2019

Submitted Date:

07/30/2019

Document Number:

690200025**FIELD INSPECTION FORM**

Loc ID 315286 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

General Comment:

On July 23, 2019, COGCC Environmental Staff (John Heil and Alex Fischer) conducted an environmental field inspection of UTAH GAS OP LTD DBA UTAH GAS CORP (Utah Gas operator #10539) Federal 10-1 Location ID 315286. Steven Hale with Utah Gas was on location at time of the inspection. Weather was sunny and temperatures about 75 degrees Fahrenheit.

The purpose of the inspection was to follow up on Remediation# 12185 to close pit ID# 104323 (Doc# 401872065).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil beneath loadout valve on 400 BBL condensate tank #80096 (See photos). Steven Hale was notified onsite.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e.	Date:	08/31/2019
Type	TRASH		
Comment:	Trash within secondary containment of tank battery. Steven Hale was notified onsite and removed trash.		
Corrective Action:	Comply with Rule 603.f .	Date:	
Type	OTHER		
Comment:	AST heater (fire tube) cover removed.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/31/2019
Type	OTHER		
Comment:	Open port on upper section of 400 BBL condensate tank #80410.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/31/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental

Spill/Remediation:

Comment: COGCC staff observed a 30 feet by 40 feet by 12 feet deep excavation located northeast of the tank battery, where the pit was located. To the south of the pit is a bermed landfarm of the excavated material measuring roughly 160 feet by 30 feet by 2 feet thick. (See photos) Operator indicated that once the landfarm material passes COGCC 910-1 criteria, it will be used to fill in the excavation.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200029	20190723 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896926