

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2019

Submitted Date:

07/31/2019

Document Number:

694900125

FIELD INSPECTION FORM

Loc ID 311643 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 950 17TH STREET, SUITE 1900
City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280074	WELL	PR	03/01/2019	GW	045-11173	VALLEY FARMS B1	PR
280352	WELL	PR	06/01/2006	GW	045-11243	VALLEY FARMS B2	PR
283980	WELL	PR	03/01/2019	GW	045-12055	VALLEY FARMS B6	PR
283984	WELL	PR	03/01/2019	GW	045-12061	VALLEY FARMS B3	PR
283985	WELL	PR	03/01/2019	GW	045-12060	VALLEY FARMS B5	PR
283987	WELL	PR	06/30/2006	GW	045-12062	VALLEY FARMS B4	PR
284240	WELL	PR	04/13/2006	GW	045-12118	VALLEY FARMS B7	PR

General Comment:

[Routine inspection](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	All tanks are missing Bbls		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	09/02/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 7		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,

Comment:	Centralized containment			
Corrective Action:		Date:		

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,

Comment:	Centralized containment			
Corrective Action:		Date:		

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	280074	Type:	WELL	API Number:	045-11173	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	280352	Type:	WELL	API Number:	045-11243	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	283980	Type:	WELL	API Number:	045-12055	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	283984	Type:	WELL	API Number:	045-12061	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	283985	Type:	WELL	API Number:	045-12060	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	283987	Type:	WELL	API Number:	045-12062	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	284240	Type:	WELL	API Number:	045-12118	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 7/31/19 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Ursa Valley Farms B Pad at Location # 311643 in Garfield County, Colorado. While there, I observed Normal production operations. During this inspection the following possible compliance issues were observed: 6 tanks missing Bbls Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified). This is a summary of inspection report.</p>	ramseys	07/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900130	694900125	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897364