

Caerus Piceance LLC
API # 045-09425
Inspection # 696600418



Photo #1 Photo at entrance of location .



Photo #2 Photo at entrance of location

Caerus Piceance LLC
API # 045-09425
Inspection # 696600418



Photo #3 Photo of tank battery.



Photo #4 photo at wellheads.

Caerus Piceance LLC
API # 045-09425
Inspection # 696600418



Photo #5 Weeds growing inside of tank containment



Photo #6 Weeds growing inside of tank containment

Caerus Piceance LLC
API # 045-09425
Inspection # 696600418



Photo #7 Berm around location is used as a BMP and needs maintenance and made to meet COGCC specifications



Photo #8 Berm around location is used as a BMP and needs maintenance and made to meet COGCC specifications.

Caerus Piceance LLC
API # 045-09425
Inspection # 696600418



Photo #9. Sediment trap on the west side of location, that all secondary perimeter ditches feed into, is in need of maintenance.



Photo #10. Sediment trap on the west side of location, that all secondary perimeter ditches feed into, is in need of maintenance.