

Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



**Photo #1 . No Battery sign at tank battery or at entrance of location.**

Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #2 Photo at entrance of location .



Photo #3 Photo at entrance of location



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #4 Photo of tank battery.



Photo #5 photo at wellheads.

Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



**Photo #6 Trash on and around location**



**Photo #7 Trash on and around location**



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



**Photo #8 Trash on and around location and in tank containment**



**Photo #9 Trash on and around location and in tank containment**



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #10 Stained soil or gravel around Separators



Photo #11 Stained soil or gravel around Separators



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #12 Stained soil or gravel around Separators



Photo #13 Stained soil or gravel around Separators

Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #14 Stained soil or gravel around production tanks



Photo #15 Stained soil or gravel around production tanks



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #16 Stained soil or gravel around production tanks



Photo #17 Stained soil or gravel around production tanks

Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #18 Stained production tanks



Photo #19 Stained production tanks



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



Photo #20 Stained production tanks



Photo #21 Stained production tanks

Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



**Photo #22 Weeds are growing inside of tank containment and on location**



**Photo #23 Weeds are growing inside of tank containment and on location**



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



**Photo #24 Erosion is evident along un-stabilized slope at the east side of location behind production tanks . Vegetation is being choked out**



**Photo #25 Erosion is evident along un-stabilized slope at the east side of location behind production tanks . Vegetation is being choked out**



Caerus Piceance LLC  
API # 045-0942510417  
Inspection # 696600420



**Photo #26 Erosion is moving off location at entrance. Ditch has no BMP in place to slow down storm water or capture sediment. Sediment is choking vegetation.**



**Photo #27 Erosion is moving off location at entrance. Ditch has no BMP in place to slow down storm water or capture sediment. Sediment is choking vegetation.**