

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401814039

Date Received:

10/29/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409

Name of Operator: PEAKVIEW OPERATING COMPANY LLC

Address: 1001 17TH ST SUITE 1050

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Wise, Wayne

720-402-3085

wwise@peakviewenergy.com

Neidel, Kris

kris.neidel@state.co.us

Walters, Steve

720-402-3081

swalters@peakviewenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689801437

Inspection Date: 07/23/2018

FIR Submit Date: 07/30/2018

FIR Status: _____

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC

Company Number: 10409

Address: 707 SEVENTEENTH ST STE 4200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312913

Location Name: Kowach Number: 24-9 SWD County: MOFFAT

Qtrqtr: SESW Sec: 9 Twp: 6N Range: 90W Meridian: 6

Latitude: 40.485521 Longitude: -107.499655

FACILITY - API Number: 05-081-00 Facility ID: 222825

Facility Name: KOWACH Number: 1-9

Qtrqtr: SESW Sec: 9 Twp: 6N Range: 90W Meridian: 6

Latitude: 40.485521 Longitude: -107.499655

CORRECTIVE ACTIONS:

1 ☒ CA# 117721

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 08/02/2018

Response: CA COMPLETED

Date of Completion: 09/10/2018

Operator Comment: Kris Neidel was contacted concerning the fresh water seepage at the wellhead. The wellhead was dug out Monday Sept 10 2018. Three abandoned lines were found and all 3 had fresh water seeping from them. One of the lines was a short piece of pipe and was pulled up. The other 2 lines were dug out and cut off as close to the road and as close to the operating pumping unit, as was prudent. Both lines were capped and welded. The excavated area around the wellhead was left open 24 hours. There was no evidence of any water seepage the next day. The excavated area was back filled with clean road base material Tuesday Sept 11 2018. As of Friday Oct 19 2018 the area around the wellhead still remains dry.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 117722

Corrective Action: Comply with Rule 603.f .

Date: 10/30/2018

Response: CA COMPLETED

Date of Completion: 10/18/2018

Operator Comment: Parts and pieces of the surplus pumping unit as well as the used tubing, were removed from the Kowach 1-9 wellsite Wednesday Oct 17 2018. The surplus pumping unit was removed Thursday Oct 18 2018.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Action Items have been taken care.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: _____

Title: Operations Engineer

Date: 10/29/2018 12:54:36 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401814039	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files