

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2019

Submitted Date:

08/01/2019

Document Number:

693200385**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 453364 _____ Murray, Richard _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100382Name of Operator: CANFIELD DRILLING COMPANYAddress: BOX 453City: FT MORGAN State: CO Zip: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453363	WELL	TA	12/15/2017	GW	077-10548	Canfield 1	EG

General Comment:[Engineering Integrity Inspection performed](#)[Inspection performed with FLIR camera GF77](#)

Inspected FacilitiesFacility ID: 453363 Type: WELL API Number: 077-10548 Status: TA Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200387	OWP 453363	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897803