

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adquate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash at Wellhead, see photo 4		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019
Type	UNUSED EQUIPMENT		
Comment:	4 strings of Tubing on the eastside of the Pumping Unit, see photo 3.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019
Type	OTHER		
Comment:	Stained Soil at Wellhead and back by the Arrow Engine, see photos 5 & 6		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	09/02/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	Appears to be plumbed to Surface		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Propane Tank at Pumping Unit. Propane tank does not have any labeling, NFPA label. See photo 2		
Corrective Action:	Install signs/labels to comply with Rule 210.d.	Date:	09/02/2019
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares Berm with Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 421912 Type: WELL API Number: 123-33110 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 07/31/2019 at approximately 14:41, I, Inspector EricaPetrie, conducted a Field Inspection at CCRP Operating INC Wagner11-65-11-1H, at Location #421908 in Weld County, Colorado. While there, I observed Type of Operation: Production During this inspection the following possible compliance issues were observed: Stained Soil at the Wellhead and back by the Arrow Engine, see photos 5 & 6, Comply with Rule 907.e. Corrective Action date of 09.02.2019 Propane Tanks is missing signs/labels, see photo 2. Install sign to comply with Rule 210.d. Corrective Action date of 09.02.2019 Tubing strings on the eastside of the Pumping Unit, see photo 3, Comply with rule 603.f. Corrective Action date of 09.02.2019 Trash at Wellhead, see photo 4, Comply with rule 603.f. Corrective Action date of 09.02.2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	petrie	08/01/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300393	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897926