

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2019

Submitted Date:

08/01/2019

Document Number:

693200388**FIELD INSPECTION FORM**

Loc ID 334643 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Elsener, Caerus		COGCC.inspections@caerus oilandgas.com	All Piceance inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466218	SPILL OR RELEASE	AC	07/22/2019		-	Sours L15W well pad 15NWSW	EG

General Comment:

[Engineering Integrity Inspection performed on July 29, 2019. In response to initial form 19 spill report Doc # 402115195](#)

Inspected Facilities

Facility ID: 466218 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel
 Variance: No Age: 1-5 Yrs Contents: Produced Water

Integrity Summary

Failures: Internal Corrosion Spills: Yes Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Observed 2" produced water dump line being cut out.
Pin hole discovered in the 6 o'clock position on tee.
Establish root cause of the failure and discuss measures that will be taken to prevent reoccurrence on the form 4.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200389	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897963