

# Allison #116S

Corrective Actions Taken on the Allison #116S for the COGCC INC.

# Allison #116S

07/30/19





Cleaned cattle guard and bladed lease access road.





Storm Water management controls have been established to stabilize storm water run on and run off. Established drainage diversion on north cut slop to stabilize erosion and site degradation, seeded disturbed areas.





Storm Water management controls have been established to stabilize erosion.  
Re-contoured and established drainage on west side of wellsite to control storm water and to stabilize erosion, seeded disturbed areas.





Storm Water management controls have been established to stabilize storm water run on and run off. Established tear drop V-ditch around location to prevent standing storm water and to control sediment on location, seeded disturbed areas.



**Note: The entire location was gridded for trash and all trash has been removed and properly disposed of.**

Tanks are labeled with current operator





 Hilcorp Energy Company

505-324-5170

Capacity 286

Produced Water

8700

1-0