

**Inspection Photos**  
**Operator: Elm Ridge**  
**Location/API #: 067-05467**  
**Date: 7-19-2019**




Photo 1. View of the beginning of Transect 1, within the project disturbance facing southward. Location is largely weeds with some desirable vegetation present. Grasses are grazed.



Photo 2. Birdseye view of vegetation at mid-point along transect. Vegetation is largely Russian thistle and other dried annual weeds.



Photo 3. View of flowering musk thistle within the project disturbance. Approximately 30 flowering individuals observed.



Photo 4. View of reference area Transect 2, facing northwestward.



Photo 5. Birdseye view of vegetation along transect midpoint. Vegetation is typical of mixed black sagebrush shrubland.