

Inspection Photos
Operator: Catamount Energy
Location/API #: 067-05455
Date: 7-29-2019



Photo 1. View of unreclaimed portion of the western project area facing eastward from the western edge. Erosional channeling is occurring across the bare soil surface.



Photo 2. View of Canada thistle (*Cirsium arvense*) infestation along the western edge of the project area. Reference area is sagebrush shrubland in the photo background.



Photo 2. View of unreclaimed eastern portion of the project area from the southern edge facing northward.