

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2019

Submitted Date:

08/01/2019

Document Number:

679704919

**FIELD INSPECTION FORM**

Loc ID 414116 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10384  
Name of Operator: GENESIS GAS & OIL COLORADO LLC  
Address: 1660 LINCOLN ST STE 2100  
City: DENVER State: CO Zip: 80246

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kimmel, March	210-363-2859	mkimmel@headwatersexp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413020	WELL	XX	08/27/2013	LO	103-11565	FGSU 4-41 WD	ND

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 7-30-2019 at approximately 11:30, inspector Rick Moran, conducted a routine well inspection at Genesis Gas & Oil Colorado well FGSU 4-41 WD in Rio Blanco county.

No corrective actions were identified.

Lease road covered in vegetation and requires walking into location.

This is a summary of inspection report 679704919.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line

# 2

corrective date

Comment: Two gas flow line risers.

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 413020 Type: WELL API Number: 103-11565 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No evidence well was drilled. Well pad visible and covered with vegetation.  
Permit to drill form 2 document 400473086 dated 8-27-2013 and expired 4-10-2016.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679704920	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898574">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898574</a>