

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2019

Submitted Date:

08/01/2019

Document Number:

696500228**FIELD INSPECTION FORM**Loc ID 320129 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: 2121 39TH AVE NE UNIT ECity: CALGARY State: AL Zip: T2E 6R7**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202757	WELL	PR	07/31/2008	OW	001-08162	CROFF 12-5	WK

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 0		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	202757	Type:	WELL	API Number:	001-08162	Status:	PR	Insp. Status:	WK
Workover									
Comment:	MIRU Duco Well Service, control well, ND WH, NU BOP, SB 2500' of tbg tallying, lay down remaining tbg tallying, MIRU e-line, RIH with junk basket/guage ring to 4870' KB, no fluid level was detected in wellbore, POOH with tools, RIH with 4 1/2" 5K CIBP and set @ 4861' KB, POOH with setting tool, load wellbore with 74 bbls of fresh water, attempt to work air and gas from well for pressure test with no success, SIW, SDFN.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696500229	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898623