

Maralex Resources Inc.

API # 077-08410

Inspection # 696600427



Photo #1 Sign is at the pump jack. No battery sign at entrance or tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #2 Photo at entrance of location . Weeds and Debris on location. No battery sign at entrance



Photo #3 Photo at entrance of location. Weeds and Debris on location

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #4 Photo of Tank battery



Photo #5 Photo of wellhead and pump jack.

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #6 Trash on location



Photo #7 Trash on location

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #8 Trash on location



Photo #9 Trash on location

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #10 Stained soil by pump jack



Photo #11 Stained soil by pump jack

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #12 Erosion is evident along un-stabilized slope on all sides of location



Photo #13 Erosion is evident along un-stabilized slope on all sides of location

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #14 Erosion is evident along un-stabilized slope on all sides of location



Photo #15 Erosion is evident along un-stabilized slope on all sides of location

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #16 Erosion is evident along un-stabilized slope on all sides of location



Photo #17 Erosion is evident along un-stabilized slope on all sides of location. Channels and rilling

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #18 Erosion is evident along un-stabilized slope on all sides of location. Sediment is moving across location.



Photo #19 Erosion is evident along un-stabilized slope on all sides of location

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #20 Channel Erosion is evident along un-stabilized slope on all sides of location. Vegetation is choked out



Photo #21 Channel Erosion is evident along un-stabilized slope on all sides of location. Vegetation is choked out

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #22 Channel Erosion is evident, Sediment moving on East side of location. Vegetation is choked out



Photo #23 Channel Erosion is evident along un-stabilized slope on East side of location. Sediment moving off location. Vegetation is choked out

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #23. Erosion moving sediment off location and down access road



Photo #24. Erosion moving sediment off location and down access road

Maralex Resources Inc.
API # 077-08709
Inspection # 696600429



Photo #25 Erosion moving sediment off location and down access road.

Run off crossing all along access road



Photo #26 Erosion moving sediment off location and down access road.

Run off crossing all along access road