

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2019

Submitted Date:

08/02/2019

Document Number:

694900143**FIELD INSPECTION FORM**Loc ID 335500 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, vanguard		aaxelson@vnrenergy.com	
, vanguard		scollett@vnrenergy.com	
, vanguard		sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293185	WELL	PR	09/18/2008	GW	045-14918	SCHIRER 13C-26-692	PR
293186	WELL	PR	09/21/2008	GW	045-14919	SCHIRER 13B-26-692	PR
293190	WELL	PR	09/15/2008	GW	045-14920	SCHIRER 13A-26-692	PR
293192	WELL	PR	09/24/2008	GW	045-14921	SCHIRER 14B-26-692	PR
293193	WELL	PR	11/12/2008	GW	045-14922	SCHIRER 14C-26-692	PR
293196	WELL	PR	09/20/2008	GW	045-14923	SCHIRER 14D-26-692	PR
293200	WELL	PR	09/23/2008	GW	045-14917	SCHIRER 13D-26-692	PR

General Comment:[Follow up inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	1 tank missing sign its laying on the ground next to tank		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/01/2019

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	no evidence of staining in tank containment from previous inspection # 689302378		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 8		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at well heads		
Corrective Action:		Date:	

Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	HEATED STEEL AST		,
Comment:	all tanks are 375 Bbls 1 not heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	YES	
Comment:	braden heads open	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293185	Type:	WELL	API Number:	045-14918	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	293186	Type:	WELL	API Number:	045-14919	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	293190	Type:	WELL	API Number:	045-14920	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	293192	Type:	WELL	API Number:	045-14921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	293193	Type:	WELL	API Number:	045-14922	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	293196	Type:	WELL	API Number:	045-14923	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	293200	Type:	WELL	API Number:	045-14917	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap		Gravel				
Waddles						
Berms		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 8/1/19 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at Vanguard Schirer, at Location # 335500 in Garfield County, Colorado.</p> <p>While there, I observed Normal production operations. No evidence of staining from previous inspection # 689302378</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>At time of inspection I observed 1 tank not labeled. Sign found on the ground by the tank now.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	ramseys	08/01/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900150	694900143	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898752